



# AIR DRYER FILTERS

DESIGNED TO CAPTURE MOISTURE AND REMOVE CONTAMINANTS


Baldwin Filters has a complete line of air dryer filters, including desiccant and desiccant/coalescing versions, to protect your equipment. Air dryer filters are designed to capture moisture and contaminants created and produced by air compressors. Keeping moisture out of the system helps to prevent possible water freezing and also potentially damaging brake valves and other vital parts. Further filtration removes oils and other contaminants, which can damage the brake system.

Desiccants are used to hold water droplets until the brake system reaches full or maximum pressure. The brake system then goes through multiple purge cycles. These purge cycles force the moisture and any contaminants built up from the system.




Desiccant/Coalescing air dryer filters include added coalescing media to remove excess oil contaminants prior to the desiccants. Removal of oil aerosols prevents contamination of the desiccants, allowing the desiccants to better remove moisture from the system.









## COALESCER AIR DRYER FILTERS

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
<b>BA5284</b> <b>Obsolete</b> 	Van Hool CL915, CL916 Buses with DAF Engines; DAF Trucks	DAF 1681575, 1821580; Donaldson P951411	<b>Thread:</b> M41 x 1.5 <b>O.D.:</b> 5 7/16 (138.1) <b>Length:</b> 6 9/16 (166.7) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5376 (Desiccant Version)
<b>BA5378</b> 	Scania Trucks	Scania 1774598; Donaldson P783753	<b>Thread:</b> 1 1/4-11 BSP-PL <b>O.D.:</b> 5 11/32 (135.7) <b>Length:</b> 7 (177.8) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5375 (Desiccant Version)
<b>BA5379</b> 	M.A.N. TGA Series, TGM Series, TGS Series, TGX Series Trucks	Volvo 20557234, 20972915; DAF 1506635; M.A.N. 81.52108.6025; WABCO R950068	<b>Thread:</b> M39 x 1.5 <b>O.D.:</b> 5 3/8 (136.5) <b>Length:</b> 6 9/16 (166.7) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5374 (Desiccant Version)

## DESICCANT AIR DRYER FILTERS

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
<b>BA5371</b> 	Haldex Pure Air Plus DA33100, DA33105, DA33110, DA33200 Air Dryers	Haldex DA33120	<b>Thread:</b> 2 1/2-12 <b>O.D.:</b> 5 7/32 (132.6) <b>Length:</b> 6 5/8 (168.3) <b>I. Gskt.:</b> 1 Included	
<b>BA5373</b> 	Ford, Freightliner, Hino, Kenworth, Peterbilt Trucks	Bendix 065624, 109493	<b>Thread:</b> 1 1/4-17 <b>O.D.:</b> 7 9/32 (184.9) Flange 8 3/8 (212.7) <b>Length:</b> 7 17/32 (191.3) <b>O-Ring:</b> 2 Attached, 2 Included	<b>Contains:</b> Grease Tube
<b>BA5374</b> 	Blue Bird, Kassbohrer, Setra Buses; DAF, E.R.F., Freightliner, IHC, Iveco, Kenworth, Mack, M.A.N., Mercedes-Benz, Peterbilt, R.V.I., Sterling, Volvo Trucks; Liebherr Cranes	Caterpillar 2032389; Iveco 2992261; Ford 4C452A131AA; General Motors 89040662; Hengst T250W; Mann & Hummel TB1374x	<b>Thread:</b> M39 x 1.5 <b>O.D.:</b> 5 1/2 (139.7) <b>Length:</b> 6 9/16 (166.7) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5379 (Coalescer Version)

## DESICCANT AIR DRYER FILTERS, CONT'D.

PART NUMBER	FITS	REPLACES	SPECIFICATIONS	NOTES
<b>BA5375</b> 	R.V.I., Scania Trucks	Scania 1384549, 1455253	<b>Thread:</b> 1 1/4-11 BSP-PL <b>O.D.:</b> 5 1/2 (139.7) <b>Length:</b> 6 31/32 (177.0) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5378 (Coalescer Version)
<b>BA5376</b> 	Van Hool CL915, CL916 Buses with DAF Engines	DAF 1391510; Hengst T200W	<b>Thread:</b> M41 x 1.5 <b>O.D.:</b> 5 1/2 (139.7) <b>Length:</b> 5 15/32 (138.9) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Related To:</b> BA5284 (Coalescer Version)
<b>BA5377</b> 	Blue Bird, Thomas Buses; Autocar, Capacity, Freightliner, IHC, Kenworth, Mack, Oshkosh, Peterbilt, Sterling, Western Star Trucks	Bendix 107794, 107796	<b>O.D.:</b> 4 17/32 (115.1) Lid 5 27/32 (148.4) <b>Length:</b> 10 23/32 (272.3) <b>O-Ring:</b> 2 Included	<b>Contains:</b> Threaded Stud: 5/8-11; Grease Tube
<b>BA5566</b> 	Volvo Trucks	Knorr-Bremse K005686, K014712, K039453; Renault 5001865404, 7421267793; Volvo 20754416, 21267818; WABCO 4329012452; Mahle AL26	<b>Thread:</b> M39 x 1.5 LH <b>O.D.:</b> 5 3/8 (136.5) <b>Length:</b> 6 9/16 (166.7) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	<b>Contains:</b> Left Hand Threads
<b>BA5592</b> <b>Obsolete</b> 	Freightliner, Mack, Volvo Trucks	Volvo 8235R950068, 85110799	<b>Thread:</b> M39 x 1.5 <b>O.D.:</b> 5 1/2 (139.7) <b>Length:</b> 6 9/16 (166.7) <b>I. Gskt.:</b> 1 Included <b>O-Ring:</b> 1 Included	
<b>BA16000</b> 	Volvo Dump Trucks, Excavators; European FH Serie Trucks	EvoBus 4294695; Haldex 78964, 83212, 92528, 93522; Iveco 42535061; Renault 5001826800; Volvo 20424148, 20546795, 20773824	<b>O.D.:</b> 6 (152.4) <b>Length:</b> 6 3/8 (161.9) <b>O-Ring:</b> 1 Included	<b>Contains:</b> 4 Bolts and Nuts

## COALESCER AIR DRYER FILTERS

BALDWIN	BENDIX	DONALDSON	FLEETGUARD	HALDEX	LUBER-FINER	WABCO
<b>BA5284 (Obsolete)</b>	–	P951411	–	–	–	4329012462
<b>BA5378</b>	–	P783753, P951419	–	–	–	4329012282, 4329012262, 4324109282
<b>BA5379</b>	5008414PG	P951413, P952185	AD27747	31005609	LFP8845	4329012252

## DESICCANT AIR DRYER FILTERS

BALDWIN	BENDIX	DONALDSON	FLEETGUARD	HALDEX	LUBER-FINER	WABCO
<b>BA5371</b>	–	–	–	DA33120, 201160	–	–
<b>BA5373</b>	65624, 109493	–	–	–	–	–
<b>BA5374</b>	109994, 5008414, 5008415	P781466, P953571	AF27817	109994K, 31004109	LFP8654	4324202202
<b>BA5375</b>	–	–	–	–	LFP5375	4324152207
<b>BA5376</b>	–	P951417	AF27853	–	–	–
<b>BA5377</b>	107794, 107796	–	–	–	–	–
<b>BA5566</b>	–	P951415	AD27748	–	–	4329012452
<b>BA5592 (Obsolete)</b>	–	–	–	–	–	–
<b>BA16000</b>	–	–	–	90588, 92528, 93522	–	–



800.822.5394 | baldwinfilters.com.

Form 375 (R 9/23) © 2023 Baldwin Filters, a Parker Hannifin Company  
Printed in the U.S.A.

**⚠ WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).