

## BALDWIN PRODUCT PICK



Baldwin Filters' PF46253 Fuel Element is designed for use with DAF, Kenworth and Peterbilt trucks, Solaris Buses and Doosan, Dynapac, Hyundai and JLG Industries equipment with Cummins and Paccar engines.

CROSS-REFERENCE	
Cummins	5335504
Fleetguard	FF266
JLG	70026453
Paccar	1707078

## APPLICATIONS

DAF	<ul> <li>LF46/LF56 FA150, LF46/LF56 FA180, LF46/LF56 FA210 (2014), LF 150, LF 180, LF 210 (2014-on) with Paccar PX-5 Euro 6 Engine;</li> <li>LF46/LF56 FA220, LF46/LF56 FA250, LF46/LF56 FA280, LF46/LF56 FA310 (2014) with Paccar PX-7 (6.7L) Engine;</li> <li>CF 230, CF 260, CF 290, CF 320, LF 230, LF 260, LF 290, LF 320 (2021) with Paccar PX-7 (6.7L) Engine;</li> <li>LF 220, LF 250, LF 280, LF 310 (2014-on) with Paccar PX-7 Euro 6 Engine;</li> <li>CF 330, CF 370, CF 400, CF 440, XF 400, XF 440 (2013-on) with Paccar MX-11 Euro 6 Engine</li> </ul>
DOOSAN	7/73 Compressor (2015) with Cummins QSF 2.8 (Final Tier 4) Engine
DYNAPAC	CC4200 VI with Cummins QSF 3.8 (Final Tier 4) Engine.
HYUNDAI	HX140LC Excavator with Cummins QSF 3.8 (Final Tier 4) Engine
JLG INDUSTRIES	1055, 1255 Telehandler with Cummins QSF 3.8 (Final Tier 4) Engine
KENWORTH	K270, K370, T170, T270, T370 (2021) with Paccar PX-7 (6.7L) Engine
PETERBILT	220, 325, 330, 337, 348 (2021) with Paccar PX-7 (6.7L) Engine
SOLARIS	Urbino 10, Urbino 12 Buses with Cummins ISBE6 Euro 6 Engine
SPECIFICATIONS	
0.D.	3 1/4 (82.6); Open Endcap: 3 3/4 (95.3)
I.D.	17/16 (36.5) One End
LENGTH	5 31/32 (151.6)
A. GASKET	[1] Attached
O-RING	[1] Included



## This product is now available. Contact your Customer Service Representative to order.

A WARNING: These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.